

M0370012
CCI TOM
0002

Attached are photographic documentation of the silt fence that was installed last week at the Pandora and the Snowball Mine sites. Thanks for giving us a heads up on this.

Christy Woodward
Environmental Coordinator

DENISON MINES (USA) CORP
www.denisonmines.com

t: (303) 389-4136 | c: (303) 549-9722 | f: (303) 389-4125
1050 17th Street, Suite 950, Denver, CO 80265

This e-mail is intended for exclusive use the person(s) mentioned as the recipient(s). This message and any attached files with it are confidential and may contain privileged or proprietary information. If you are not the intended recipient(s) please delete this message and notify the sender. You may not use, distribute print or copy this message if you are not the intended recipient(s).

From: Danny Flannery
Sent: Monday, April 20, 2009 9:48 AM
To: Christy Woodward
Subject: silt fence @ Pandora and Snowball

Danny Flannery
Mine Permit Specialist

DENISON MINES (USA) CORP
www.denisonmines.com

t: 435-678-2221 x111 | f: 435-678-2224
6425 S. Highway 191, PO Box 809, Blanding, UT 84511

This e-mail is intended for exclusive use the person(s) mentioned as the recipient(s). This message and any attached files with it are confidential and may contain privileged or proprietary information. If you are not the intended recipient(s) please delete this message and notify the sender. You may not use, distribute print or copy this message if you are not the intended recipient(s).

0002

Erosion Control at base of waste rock for Pandora and Snowball Mines.

Project completed on 04-17-2009

These pictures show the silt fence which has been installed at the base of the Pandora waste rock pile. The straw berm installed last summer was destroyed by cattle during the winter.



The fence is wire backed and buried into the ground.





Waste rock storage pile at the Snowball Mine



Taken from the top of the waste rock pile. Some of the straw berm remained undisturbed but most was destroyed.

